

PN : BJHCS-K5

**IPN = 50A - 100A - 150A - 200A -
300A - 400A - 500A - 600A**

Features

- Open loop
- Small size
- Easy installation
- Frame mounting
- Internal and external reference
- High immunity to external interferences
- Supply voltage : +5V DC
- Voltage output
- Through hole primary
- Can be customized

Applications

- AC/DC variable speed motor driver
- Battery applications
- Uninterruptible power supplies (UPS)
- Power supplies for welding applications



ELECTRICAL DATA


BJHCS-K5-...	50A	100A	150A	200A	300A	400A	500A	600A
Nominal rms current I_{PN} (A)	50	100	150	200	300	400	500	600
Sensed current range I_{PM} (A)	±100	±200	±300	±400	±600	±800	±900	±900
Output voltage @ I_P (V)	$V_{OE} \pm (0,625 * I_P / I_{PN})$							
Supply voltage V_C (Vdc)	+5 V ±5%							
Static current consumption I_C (mA)	15							

ACCURACY DYNAMIC PERFORMANCE

GENERAL & ISOLATION CHARACTERISTICS

Accuracy X_G @ I_{PN} , T=25°C	± 1	%	Operating temperature range	-40 to +85	°C
Offset voltage V_{OE} @ $I_P=0$, T=25°C	2,5±0,025	V	Storage temperature	-40 to +125	°C
Offset voltage drift @ -40 to +85 °C	$I_{PN}=50A$	≤ ± 2	Insulation voltage (50Hz, 1mn)	2,5	KV
	Other	≤ ± 1			
Hysteresis offset voltage V_{OH} @ -40 to +85 °C	$I_{PN}=50A$	± 20			
	Other	± 15			
Linearity error ϵ_L	≤ 1	% FS			
Response time t_r	≤ 3	µs			
di/dt accurately followed	>100	A/µs			

DIMENSIONS



MECHANICAL CHARACTERISTICS

General tolerance	± 0,2 mm
Primary square through hole size	20,5 x 10,5 mm
Transducer fastening	M4
Recommended fastening torque	< 1,5 Nm
Terminal connection	Molex 5045-04A

Cautions :

- I_S is positive when I_p flows in accordance with the arrow direction (see the top of the sensor);
- Primary conductor temperature should not exceed 100°C;
- Best dynamic performances (di/dt and response time) are achieved with a single electrical conductor completely filling the through hole;
- To achieve the best magnetic coupling, the primary winding must be wound around the top edge of the sensor.

Required connection circuit :

- See drawing above.

WARNING : Incorrect wiring may cause damage to the sensor.